Bathing establishment fact Sheet

Name of bathing establishment	COLOMBO ALESSANDRO
Address	Via Adelaide Ristori, 5
City	Viareggio (LU)
Contacts	Tel +39 0584 46574
Website	https://bagno-colombo-alessandro.business.site/

TESTED BY: Handy Superabile - Social Promotion Association in summer 2023

Please note The following information refers to the verification date shown at the bottom of each sheet. The Association is not responsible for any significant changes made to the property after the visit.

Summary

Bating establishment Fact Sheet 1
Arrival at the facility 2
Private/public parking 2
Pathway from the parking lot to the main entrance 2
Reception welcome 3
Bar/restaurant 3
Internal pathways and common services 4
Internal pathways 4
Toilet and shower accessible to guests with reduced mobility 5
Changing room 6
Beach 7
Children's play area 8
Pool 8
Medical practices/health facilities 9

Arrival at the facility

Private/public parking

Presence of private parking	NO
Public parking nearby	YES about 50/100 meters away
Presence of parking space reserved for people with disabilities	YES
Type of parking lot	ASPHALT

Pathway from the parking lot to the main entrance

Pathway from the parking lot to the entrance	Via 2 steps that can be overcome via a ramp, length 700 cm, width 100 cm, slope 6.9%, handrail on the right
There are indicators and tactile maps	NO
Useful width of door/entrance passage	greater than 90 cm

Reception welcome

Umbrella booking system	☐Via the web ☒Via telephone ☒On site
Presence of multilingual staff	not detected
Presence of plant plan with legend of services available	NO
Presence of visuo-tactile map	NO
Noticeboard/information panels at an average height of 130 cm in a well-lit area and a character size of at least 14 dpi with a contrast ratio greater than 4.5:1	NO
The staff has undergone training on welcoming people with various disabilities	NO

Bar/restaurant

Type of venue	Bar/restaurant
Access to the venue	via ramp: length 700 cm, width 100 cm, slope 6.9%., handrail on the right while the veranda can be reached on level ground from the corridor on the side of the ramp
Useful width of door/entrance passage	greater than 90 cm
Bar counter	100 cm high
Type of tables	4 legged and centrally supported
Space under the floor tables	67 cm
Multilingual menu	not detected
Menu with large print characters	NO
Braille menu	NO

Table service for people with disabilities	YES
Availability of food for celiacs	☐bread☐pasta☐cookies☐ice creams ☐pre-packaged foods

Internal pathways and common services	
Internal pathways	
Indicate whether the pathways connecting the entrance to the beach are flat or with ramps in addition to those already described	obstacle-free pathways

Toilet and shower accessible to guests with reduced mobility

Number of toilets accessible/usable by guests with reduced mobility	1
Access to the venue	Via the same ramp that leads to the bar restaurant: length 700 cm, width 100 cm, slope 6.9%, right handrail
Useful width of entrance door	87 cm
Toilet height	50cm
Open front toilet seat	YES
Support handles	on both sides of the toilet
Flexible shower next to the toilet	YES
Free space on the sides of the toilet	to the left greater than 90 cm To the right 30cm Front greater than 90 cm
Electric bell/telephone	YES
Washbasin with space underneath for a wheelchair	70cm
Height from the ground to the lower edge of the mirror	not sufficient for use by people in a wheelchair
Baby changing table	not detected

	
Shower accessible to guests with reduced mobility available	Yes, shared with the toilet room
Shower type	open type
Floor-level shower	YES
Shower chair	missing
Support handle	YES
Presence of shower head or latch	fixed shower head
Electric bell/telephone	YES
	Adapted bathroom

Changing room

Changing room accessible to guests with reduced mobility available	NO

Beach

Type of beach	sand
Access to the beach	flat
Walkway to reach the umbrellas	YES
Type of walkway	made of PVC
Walkway width	90cm
and the umbrella station to facilitate the passage and parking wheelchair	
Amphibious beach chair available for helping people with reduced mobility to enjoy swimming (owned by the establishment or by association)	YES

Children's play area

Children's play area	inaccessible to children with reduced mobility due to the sandy bottom
There are games for children with reduced mobility	NO
	Children's play area on sandy bottom

Pool

The property has a swimming pool	NO

Medical practices/health facilities

Hospitals near the facility	**Versilia Hospital SS 1, 335, 55049 Camaiore LU Telephone: 0584 6051**
Other healthcare facilities	**ASL Health District No. 12** Viareggio Place Buon Consiglio Viareggio Tel. 0584.6056353 **Dialysis service in Pisa atCISANELLO HOSPITAL** Dialysis therapy department (hemodialysis – peritoneal dialysis) in the period June - September Holiday Dialysis Service with availability of n. 6 beds tel. 050 997250 – 997253 – 997256

TESTED BY: Handy Superabile - Social Promotion Association- in summer 2023